
NEW SITE IDENTIFICATION

Pa	rt A – To Be Completed By Observer		
1.	Person Initiating Report: Jacob Harris	Phone: 526-1877	
	Contractor WAG Manager: Douglas Burns	Phone: 526-4324	
2.	Site Title: 037, Lids by Experimental Field Station		
3.	Describe the conditions that indicate a possible inactive or unreported waste site. Include location and description of suspicious condition, amount or extent of condition and date observed. A location map and/or diagram identifying the site against controlled survey points or global positioning system descriptors shall be included to help with the site visit. Include any known common names or location descriptors for the waste site. Two lids are located 300 ft. north of the powerline road near the experimental dairy farm. During the July 1999 site visit, a		
	galvanized metal trash can lid and an unknown stainless steel container was observed. The GPS coordinates of this site are E302115.01 by N708111.8. The reference number for this site is 037 and can be found on the summary map as provided.		
Pa	rt B – To Be Completed By Contractor WAG Manager		
4.	Recommendation:		
	This site meets the requirements for an inactive waste site, requires investigation, and should be included in the INEEL FFA/CO Action Plan. Proposed Operable Unit assignment is recommended to be included in the FFA/CO. WAG: 10 Operable Unit: 10-08		
	This site DOES NOT meet the requirements for an inactive windled in the INEEL FFA/CO Action Plan.	aste site, DOES NOT require investigation and SHOULD NOT be	
5.	Basis for the recommendation:		
	The conditions that exist at this site indicate the potential for an into or Disturbance of Suspected Inactive Waste Sites.	active waste site according to Section 2 of MCP-3448 Reporting	
		•	
	The basis for recommendation must include: (1) source description concern; and (4) descriptions of interfaces with other programs, as		
6.	Contractor WAG Manager Certification: I have examined the propositive the information to be true, accurate, and complete. My recommendation to be true, accurate, and complete.		
Na	me: Junes E. Junes Signature:	E Date: 5/25/00	

NEW SITE IDENTIFICATION

Part C - To Be Completed By INEEL FFACO/CO WAG Managers				
7. WAG Operable Unit:				
DOE WAG Manager Concurrence:	M Concur with recommendation.	☐ Do not concur with the recommendation.		
Signature: Patti Krompa		1		
Date: 5\3\\00	_			
EAP WAG Managers Concurrence:	Concur with recommendation.	☐ Do not concur with the recommendation.		
Signature: tee Pout	_			
Date: 6/5/00	_			
State of Idaho WAG Managers Concurrence:	Concur with recommendation.	☐ Do not concur with the recommendation.		
Signature: Herry Wentes				
Date: 10-14-00	_			
Explanation follows:				
		•		
Part D – To Be Completed By The INEEL FFA/CO Responsible Program Managers (RPM's)				
8. FFA/CO RPM's Concurrence:				
For DOE-ID				
Name: Kathleen Hain Signature: Zattleen	E Hain Date: 7/12/00	 Concur Do not concur. Explanation follows: 		
For EPA Region X				
Name: Wayne Pierre Signature:	Villa Date: 715 100	Concur		
For State of Idaho		Do not concur. Explanation follows:		
Name: Dean Nygard Signature:	M/c1-90 Date: 628100	Concur		
		Do not concur. Explanation follows:		



MISC-37, Lids by Experimental Field Station